



Inspection Report

A. GENERAL INFORMATION:

Report No.:	2026-10-22-plate-PO#CZ260930XQ-1	
Client:		
Supplier:	Cuzi Industry Co., Limited	
Product Description:	MELAMINE FACED SLOTTED MDF BOARD ALUM CHANEL #Z7120	
P.O. NO.:	CZ260930XQ-1	
Item :	8'x4'x17mm white 8'x4'x17mm brown ALUM CHANNEL	
P.O. Quantity:	6980pcs	
Qty Presented:	6980pcs	
Service Performed:	Pre-Shipment Inspection	
Inspection Date:	October 22, 2026	
Inspection Location:	Suqian, Jiangsu	
Inspector(s):	David Ge	
Sample available:	NO	

B. Inspection Summary:

	PASSED	FAILED	PENDING	N.A.	REMARK
1. Quantity	✓				
2. Style , material , color:				✓	
3. Workmanship/appearance/function	✓				
4. Packing	✓				
5. Marking/label	✓				
6. Data measurement/field tests	✓				
7. Client Special Requirement	✓				

C. Remark:

Problem Remarks:	
1	No samples approved as reference during inspection.
General Remarks:	
2	The product has not been packaged yet.





华检检验

China Inspection Service

Address: Room B4858, 24F, No.59, Zhu ji Road, Tian he District, Guangzhou city, Guangdong Province, China
TEL: 86-020-28912259 86-13602211515
Email: chinainspection@vip.163.com

CONCLUSION:

Pass

(Client has the final decision to Reject or Approve)

1. Quantity Check:

Art. No.	Order Qty.	Presented PCS		Presented CTNS	
		Packed	Not Packed	Packed	Not packed
8'x4'x17mm white	750	0	750	/	/
8'x4'x17mm brown	230	0	230	/	/
ALUM CHANNEL	6000	6000	0	/	/
Total:	6980pcs	6000pcs	980pcs	/	/
Result:	Pass				
Remark:	The product has not been packaged yet.				

2. PRODUCT CONFORMITY:

CONFORMITY	YES	NO	PENDING	REMARK
2.1 Style conformity:				✓
2.2 Material conformity:				✓
2.3 Color conformity :				✓
Remark:				
1.No samples approved as reference during inspection.				

3. WORKMANSHIP APPEARANCE / FUNCTION INSPECTION FINDINGS:

Inspection standard:	ANSI/ASQ Z1.4	AQL	Accepted	Defects Found	Result	
Sampling Plan:	Normal Single	Critical: 0	0	0	PASSED	
Inspection Level:	Level II	Major: 2.5	10	0	PASSED	
Sample Size:	200pcs	Minor: 4.0	14	0	PASSED	
Inspection found	☒	PASSED	Due to	☒	WITHIN AQL	
	☐	FAILED		☐	BEYOND AQL	
	☐	PENDING		☐	REMARKS	
Inspected Samples Size and Cartons						
Item No.	Quantity	Cartons		Item No.	Quantity	Cartons
8'x4'x17mm white	8	-		8'x4'x17mm brown	22	-
ALUM CHANNEL	170	-		-	-	-

Item No.	Ref. Pic.	Defects Description:	Critical	Major	Minor
-	-	-	0	0	0
Total Defects Found:			0	0	0
Max Defects Allowed:			0	10	14
Sample Size:			200	200	200





Remarks:	-
Note: A Defective is defined as a unit of product that contains one or more defects. A Defect is defined as any non-conformance of the inspected unit of product with specified requirements. A single defect is taken into account per each defective unit; only one most serious defect is taken into account per each defective unit	

Defect pictures			
ITEM NO.:		-	
NIL		NIL	
1.	NIL	2.	NIL

4. PACKING				
	YES	NO	PENDING	REMARK
4.1 if package of carton is scientific rationality	✓			
4.2 Individual packing	✓			
4.3 Export packing conformity :	✓			
Remark: The product has not been packaged yet.				

5. MARKING/LABEL				
	YES	NO	PENDING	REMARK
5.1 Bar code:	✓			
5.2 Shipping mark conformity:	✓			
5.3.Side mark conformity:	✓			
5.4 Main label :	✓			
Remark: The product has not been packaged yet.				





华检检验

China Inspection Service

Address: Room B4858, 24F, No.59, Zhu ji Road, Tian he District, Guangzhou city, Guangdong Province, China
TEL: 86-020-28912259 86-13602211515
Email: chinainspection@vip.163.com

6. Data measurement/Tests (as applicable for specific product/order)

SKU No.	Carton size	Carton weight	Inner package size	Inner package weight	Product size	Product weight
8'x4'x17mm white	-	-	-	-	243*122.4*1.709 cm	28.2kg
8'x4'x17mm brown	-	-	-	-	244*122.4*1.709 cm	28.3kg
ALUM CHANNEL	-	-	-	-	244*2.7*1.322cm	0.195kg



7. Tests (as applicable for specific product/order)

No.	Test name	Inspection standard	Test Quantity	Result
1	Assembly Test	S-2	8pcs	Pass
2	Smelling Check	Level II	200pcs	Pass


8. Client Special Requirement

SKU No.	Barcode No. (Printing)	Barcode No. (Scanning result)	Inspect Quantity	Defect quantity (Major+Minor)	Defect rate
-	-	-	-	-	-
Total:	-	-	-	-	-

9. Photos: Box text/Marks/Labels/Hangtag/Barcode

1	Art. No.:	8'x4'x17mm white
		
1.	Product view	
2.	Product view	






3. Product view



4. Product view



5. Product view



6. Product view




7. Product view




8. Product view






9. Product view



10. Product size check




11. Product size check



12. Product size check



13. Product size check



14. Product size check







15. Product weight



16. 28.2kg

2 Art. No.: 8'x4'x17mm brown



17. Product view

18. Product view



19. Product view

20. Product view






21. Product view




22. Product view




23. Product view



24. Product view




25. Product size check



26. Product size check






27. Product size check



28. Product size check



29. Product size check



30. Product size check



31. Product weight check




32. Product weight check

3 Art. No.: ALUM CHANNEL





33. Product view



34. Product view



35. Product view



36. Product view



37. Product view



38. Product size check





39. Product size check




40. Product size check



41. Product size check



42. Product size check



43. Product size check



44. Product size check





45. Product size check



46. Product size check



47. Product weight check



48. Product weight check




49. Smell check



50. Smell check






51. Assembly Test



52. Assembly Test



53. Assembly Test



54. Assembly Test

10. Other pictures



55. Factory picture




56. Inspection site






57. Inspection site



58. Inspection site




59. Inspection site



60. Inspection site



61. Inspection site



62.

The end of the Inspection Report

